



Laguna False Tyre Pressure Alarm

False low pressure alarms on Laguna 2 up to 02 model year are cured by modifying the pressure alarm tolerances of the UCH module by selecting "Activating Threshold Modification" on the Diagnostic tool.

This will modify/raise the pressure warning system threshold to prevent false alarms.